## Part Number Update

Bulletin No: PNU-123-001

Effective Date: September 22, 2009 Cancels: PNU-123-000 dated 9/29/08

Subject: Bendix® EC-30™ Electronic Control Unit (ECU) Service Parts

Below is a list of service replacement ECUs for Bendix® EC-30™ controllers. All of the replacement EC-30 ECUs shown support PLC (Power Line Carrier communications).

> See Top Surface of Electronic Controller for Inscribed Part Number (or, in some cases, a white applied label)



EC-30<sup>™</sup> Electronic Controller

Original Part No.	Replacement Part No.
801166	801167
801173	801335
801174	801335
801176	801177
801178	801179
801181	801180
801201	801199
801204	801202
801207	801199
801208	801199
801209	801199
801210	801202
801211	801202
801212	801202
801225	801227
801226	801228
801237	801238
801334	801335
5006819	801177
5007575	801177
5010174	801167
5010175	801167
5010178	801335
5010292	801180
5010293	801180
5010296	801180
5010307	801201

Original Part No.	Replacement Part No.
5010308	801199
5010309	801199
5010310	801199
5010314	801227
5010318	801180
5010345	801180
5010346	801202
5010347	801202
5010348	801202
5010349	801202
5010350	801202
5010351	801202
5010356	801238
5010360	801180
5010364	801167
5010366	801228
5010428	801167
5010431	801335
5010465	801177
5010467	801179
5011100	801335

